


Instruction

Replacement of Program EPROMS in the AMS Display

Please make the following steps:

1. Remove power plug.
2. Remove the black cover plate from the backside of the display.
3. Carefully lever both EPROMS out of the IC-socket.
4. Insert new EPROMS.
EPROM 0 on the right side, and EPROM 1 on the left side.
Marking upwards.



5. Screw on the cover plate.
6. Connect power plug.

	ADOLF THIES GmbH & Co. KG			
	Hauptstraße 76 P.O. Box 3536 + 3541 Phone ++551 79001-0 www.thiesclima.com	37083 Göttingen Germany 37025 Göttingen Fax ++551 79001-65 info@thiesclima.com		

- Alterations reserved -